

# Oil Field Environmental Incident Summary

**Incident:** 20131211065031      **Date/Time of Notice:** 12/11/2013 06:47

**Responsible Party:** Oasis Petroleum

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** GNR 10-3H

**Field Name:** ROSEBUD

**Well File #:** 23947

**Date Incident:** 12/8/2013      **Time Incident:** 1100

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 153

**Rng:** 102

**Sec:** 10

**Qtr:**

**Location Description:**

**Submitted By:** Dan Grafton

**Received By:**

**Contact Person:**

1001 FANNIN STE 1500  
HOUSTON, TX 77002

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Unknown

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	<b>3</b>	<b>barrels</b>	<b>3</b>	<b>barrels</b>		
<b>Brine</b>	0	barrels	0	barrels		
<b>Other</b>	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

Oil

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

**Areal Extent:**

***Potential Environmental Impacts:***

***Action Taken or Planned:***

Valve replacement

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 12/11/2013    ***Status:*** Reviewed - Follow-up Required

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Containment of release reported as unknown from a valve malfunction. Followup is necessary to determine containment and, if off location, adequate cleanup.

---

***Date:*** 2/6/2014    ***Status:*** Inspection

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

2/6/14 - 11:05 on location. All valving areas clean. No further indication of released oil. GPS location 48deg 05.095min N, -103deg 47.159min W. No further inspection required.